



4/20/2008

RELIABILITY MONITOR REPORT  
FOR

**DAL B8 Silicon Gate CMOS**

**MAXIM Integrated Products**

120 San Gabriel Dr.  
Sunnyvale, CA 94086

This Report was prepared by  
Maxim Reliability Engineering

**Summary:**

The data in the tables that follow was generated as the result of an on-going Process Reliability Monitor. The specific products in this process monitor are:

DS2413	DS8007	DS8113
--------	--------	--------

The calculated failure rate for devices using this process is:

**FAILURE RATE:**                      **MTTF (YRS): 15863**                      **FITS: 7.2**

The parameters used to calculate this failure rate are as follows:

**Cf: 60%**                      **Ea: 0.7**                      **Tu: 25 °C**

The reliability data follows and in this section is the detailed reliability data by stress. The reliability data section includes the latest data available. This report covers data between 4/1/2007 and 3/31/2008 .

---

**Process Information:**

Process Description:              DAL B8 Silicon Gate CMOS

---

**OPERATING LIFE**

DESCRIPTION	DATE CODE	TEST VEHICLE	CONDITION	READPOINT	QUANTITY	FAILS	FA NO
HIGH TEMP OP LIFE	0713	DS2413	125C, 5.25 VOLTS	1000 HRS	45	0	
HIGH TEMP OP LIFE	0724	DS8007	125C, 6.0 VOLTS	1000 HRS	45	0	
HIGH TEMP OP LIFE	0744	DS8113	125C, 6.0 VOLTS	1000 HRS	45	0	
				<b>Total:</b>		<b>0</b>	

**FAILURE RATE:**                      **MTTF (YRS): 15863**                      **FITS: 7.2**